

## ABSTRACT OF THE DISCLOSURE

Output wires are all led out of Address 1 in slots and vibration-absorbing bent portions are formed on all of the output wires between a leader portion led out from a rear-end coil end group and a tip portion of the output wire.